

Scope of Work

1. Provide security measures adequate to prevent unauthorized access to the facility.
2. Prepare a Health and Safety Plan consistent with applicable Occupational Health and Safety Administration (OSHA) regulations to be followed when implementing the Removal Program.
3. Inspect the facility on a regular basis not less than three (3) times per week for evidence of spillage or leakage from containers (including vats, bags, bottles, and drums). Any noted spillage or leakage shall be cleaned up and containerized. Empty containers shall be overpacked in larger containers.
4. Prepare a plan for collecting samples of the materials to be removed pursuant to this Order (e.g., the contents of the containers). The types of analyses and number of samples shall be determined based on the requirements of the disposal facility which will receive these materials.
5. Prepare and implement a plan to avoid the intentional or unintentional mixing of incompatible materials.
6. Remove and dispose of all hazardous substances and all containers of all hazardous substances or which have held hazardous substances from the facility. The Removal Program shall be consistent with current EPA removal policies and criterion.
7. Prepare a plan for decontaminating the facility (e.g., cleaning, washing, etc.) and implement the plan after the materials have been removed.

268796



6/12
10:00
Lesore

Telecopier Request REGION 2

RESPONSE AND PREVENTION
Edison, New Jersey

TO: Howard Orleans
PHONE: 264-7611
BLDG. LOCATION: _____

FROM: Diwayne Hunter
SUBJECT: Synkote Seeps at WWT
PHONE: 202-906-6800

NUMBER OF PAGES TO FOLLOW: 1
FOR ASSISTANCE CALL: 264-4115
DATE SENT: 6/12/89
TIME: 0930

EPA REGION 2 FOR NEW JERSEY